

RECEIVED

JAN 31 1992

DIVISION OF  
OIL GAS & MINING

STATE OF UTAH  
DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL, GAS AND MINING  
355 West North Temple  
3 Triad Center, Suite 350  
Salt Lake City, Utah 84180-1203  
Telephone: (801) 538-5340  
Fax: (801) 359-3940

ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

I. GENERAL INFORMATION

1. Report Time Period: From (mo./yr.) 1/91 To (mo./yr.) 12/91
2. DOGM File Number: M / 045 / 030
3. Mine Name: Timpie Solar Ponds
4. Mineral(s) Mined: NaCl - Halite
5. Legal Description (Location of Lands Affected):  
22, 23, 24, 25, 26, 27  
1/4, 1/4, Section \_\_\_\_\_, Township T1N, Range R7W  
1/4, 1/4, Section \_\_\_\_\_, Township \_\_\_\_\_, Range \_\_\_\_\_  
1/4, 1/4, Section \_\_\_\_\_, Township \_\_\_\_\_, Range \_\_\_\_\_
6. Name of Operator or Company: Akzo Salt of Utah
7. Permanent Address: Akzo Salt of Utah  
1428 James Palmer Road  
Lake Point, Utah 84074

8. Company Representative (or designated operator):

Name: Dan Bauer  
Title: Plant Manager  
Address: 1428 James Palmer Rd, Lake Point, Utah 84074  
Phone: (801) 250-1151

☐ Please check if any of the above information has changed since previous year.

II. MINING AND RECLAMATION

1. Was the mine active during the past year? Yes ☒ No ☐
2. If active, how much ore or mineral was mined? 241, 843 Tons
3. How much new or additional acreage was affected during past year? None
4. Briefly describe any new or additional surface disturbances that occurred during the past year. This description should include the type of work performed, and volume of material moved.  
Two buildings were constructed during 1991. A heavy equipment  
maintenance shop and a public load facility. Both facilities are  
located on the 100 acres listed on plant site on reclamation plan.
5. How much acreage was reclaimed during past year? None
6. Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results.  
None



17,100 Acres Ponds

7. What is the total disturbed acreage at years end? 100 Acres Plant Site

8. Briefly summarize mining and reclamation planned for the upcoming year.

The mining activities will remain the same during 1992. Additional  
buildings are being planned at the Plant Site in the area noted as  
Warehouse. No concurrent reclamation is being planned.

**NOTE:** Section III., "Additional Information" applies only to large mining operations.

### III. ADDITIONAL INFORMATION


1. An updated surface facilities map should be attached if there have been significant changes since the previous map was submitted.
2. Any monitoring results or other reports that are required under the terms of the approved notice of intention should also be attached.

### IV. SIGNATURE REQUIREMENT

I hereby certify that the foregoing is true and correct.

Name (Typed or Print): Dan Bauer

Title of Operator: Plant Manager

Signature of Operator: 

Date: 1/29/92

jb  
MR-AR